

[illegible]

→ Direction    1 = Vehicle 1    2 = Vehicle 2    Pedestrian

ie: → 1    → 2    →

**Crash Diagram:**

Auburn St

Commonwealth Ave Carriage Lane

Commonwealth Ave

← N →

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

**Crash Narrative:**

Operator of MV#1 stated he was travelling westbound on Commonwealth Ave with his dog in the front seat when he slid on ice and off the roadway. The roadway was wet from previous snow fall but was very well plowed and sanded. MV#1 hit a curb, drove through a snowbank, hit a tree with the left front of his vehicle and then hit a pole with the right front side of his vehicle. The car then came to a rest in the median. The operator appeared confused by the accident and did not realize the extent of the damage to his car. He asked what he had hit. He continuously asked if it was driveable even though the entire front end was totaled. He was able to provide me with his license and all pertinent information but spoke in a slow manner. There was no odor of alcohol. Operator declined medical attention. When asked if he was on any medication he stated he was on heart medication. We were able to contact the operator's son who was transported to the scene and stated the

(Continued on next page)

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code 35

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length 39

**Hazmat Information:**

Placard 40 Material 1 digit # 41 Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code 42

→ Direction    1 = Vehicle 1    2 = Vehicle 2    Pedestrian

ie: → 1    → 2    →

### Crash Diagram:

If Crash Did Not Occur  
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



### Crash Narrative:

operator had previously suffered a stroke. David Donahue arrived on scene towed the vehicle to Tody's. A licensed driver picked up the operator. A search of the immediate area yielded negative results for ice in the roadway. A request for Immediate Threat License Suspension/Revocation was filed.

### Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

### Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

### Truck and Bus Information:

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code 35

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length 39

#### Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code 42