

[illegible]

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

Unit 1

1216 Washington st

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

○

Crash Narrative:

On Tuesday, March 5th 2019, at 7pm, I, Officer Brooks, responded to 33 Walker street for a past hit and run. On my arrival I spoke with the operator of MV1 (MA REG 28DG82), who stated his vehicle was struck at 3pm this afternoon in front of 1296 Washington street. His vehicle was allegedly struck by a bus, unknown plate or company, that was traveling eastbound on Washington street. The bus caused the front drivers side quarter panel to be ripped from the vehicle. MV1 was towed by AAA.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code