

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

Beacon Street

Unit 1

Unit 2

P.O.I.

Frame It 1645 Beacon Street

NOT TO SCALE

→ N →

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

○

Crash Narrative:

The operator of MV1 stated that he was making a delivery at Frame It and double parked MV1 facing West bound in front of 1645 Beacon Street. The operator of MV1 then stated that he left Frame It and went into another store MV1 was still parked out front. When he came out moments later MV1 was not where it had been parked and had rolled across the street crashing into MV2 which was parked facing east bound on Beacon Street. MV1 sustained minor damage to rear bumper while MV2 sustained major damage to the rear bumper. Neither operator was involved in the crash so medics were not notified. MV1 left the scene driven by its operator and MV2 was towed by Todys. The operator of MV2 was not on scene and unreachable at the time of this report.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # S40727 (From Vehicle Section)

Carrier Name FEDEX Carrier Issuing Authority Code 35

Address 5 MEGAN COURT City MENDON St MA Zip 01756

US DOT #: 270617 State Number MA Issuing State MASSA ICC #: 99 Interstate 36

Cargo Body Type Code 3 Gross Vehicle Weight 2

Trailer Reg #: 37 Reg Type 38 Reg State 39 Reg Year 39 Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name 41 Material 4 digit # 42 Release code 42

HAGAI BRANDON 30619 NEWTON POLICE DEPART 03/21/2019

Police Officer Name (Please Print) Signature ID/Badge # Department Precinct/Barracks Date

CDP1 11 -24:00