



→ Direction    1 = Vehicle 1    2 = Vehicle 2    Pedestrian

ie: → 1    → 2    →

**Crash Diagram:**

23 Nahanton St

Nahanton St

P.O.I.

V1

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

**Crash Narrative:**

Vehicle 1 was travelling southbound on Nahanton St. The operator of vehicle 1 lost control to the vehicle, due to the wet road conditions, and struck the telephone pole (#6/4) in front of 23 Nahanton St. There was no damage to the telephone pole. There was moderate damage to the front of vehicle 1. I observed air bag deployment to the front and passenger side of the vehicle. No one was injured, and the vehicle was towed by Tody's to their lot.

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property
EVERSOURCE, ,	160 CALVARY ST WALTHAM, MASSACHUSETTS		4	ONE UTILITY POLE (#6/4)

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate

Cargo Body Type Code  Gross Vehicle Weight

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code

TIMOTHY ROCHE      NEWTON POLICE DEPT      05/05/2019

Police Officer Name (Please Print)      Signature      ID/Badge #      Department      Precinct/Barracks      Date

CDP1 11 -24:00