

→ Direction 1 = Vehicle 1 2 = Vehicle 2 ○ Pedestrian

ie: → 1 → 2 → ○

Crash Diagram:

Parmenter Rd

Fuller St

Unit 2

Unit 1

STOP

STOP

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

○

Crash Narrative:

On Saturday, May 15th 2019, at approximately 12:09am, I, Officer Brooks, responded to a 2 car MVA at the intersection of Parmenter road and Fuller street. Upon my arrival I spoke with the operator of MV1(MA REG 8TA771), who stated he was traveling southbound on Parmenter road when he was struck by MV2(MA COM V23569) which had been traveling eastbound on Fuller street and was attempting to cross Parmenter road. I observed damage to the drivers side front bumper of MV1, in the area of the headlight assembly. I then spoke with the operator of MV2 who stated she was crossing over Parmenter road when MV1 came "flying" towards her and struck her driver's side in the area of the door and front wheel well/quarter panel. There was minor damage to the area, however the driver's side door would not open. The damage to both vehicles was not consistent with how the operators described the accident. Both vehicles

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

If Crash Did Not Occur
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



Crash Narrative:

had been moved after the accident before my arrival, so I was unable to see how the accident had occurred.

Based on the damage, the accident appeared to be a sideswipe going in opposite directions versus the "T bone" style collision the operators gave.

There were no injuries in the accident, and both vehicles were driven from the scene.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42