[Poli	ice Use Only		Commonwea	lth o	of Mass	achu	isetts	5		RM	V Docur	nent Number	
	Date of Crash 10/25/2019	Time of Crash 14:17 24HR	NEWTON	MIOTOI		icle Cra Report	sh	Number Vehicles 2		red Lat	ed Limi itude _ ngitude_		State Police Local Police MBTA Police Other:	Xi D
			RSECTION:		LOCA	_	>		NO				CTION:	2
						EAST	361	L	WAS	HINGT	ON ST			2
1 1	Route# Direc	oute# Direction Name of Roadway/Street			Route# Direction Address # Name of Roadway/Street					/Street				
	At				Feet NSEW of or Exit Number							- ├-		
	Route# Direction Name of Intersecting Roadway/Street				Mile Marker Exit Number Feet NSEW of							-		
2	Also at Intersection with					Route# Intersecting Roadway/Street Feet N S E W of								- -
² 99	Route# Direction Name of Intersecting Roadway/Street				Landmark								$-\frac{3}{2}$	
3 1	X Vehicle 1	Vehicle1 1_#Occupants					·							7
	Venicie 1	roccupants		Case	Number		19	900001093						_
	License # St MA DOB/Age 18 18 19				Reg # T34275 Reg Type PAN Reg State MA Veh Year 2017 Veh Make TOYOTA Veh Config. 2								-	
	Sex_M_ Lic.		Lic. Restriction	S CDL Endorsment								_ Veh Co	nfig. 2	\vdash
⁴ 1	Operator MA	perator MALDONADO ANTHONY Last First Middle 52 SYCAMORE ST			Owner APPLUS TECHNOLOGIES Last First Middle Address 600 CORPORATE PK DR								- 7	
	Address 52 SYCAMORE ST City SPRINGFIELD State MA Zip 01109										C+-/	МО	7in 63105	-
	City State S				City ST LOUS State MO Zip 63105 Vehicle Action Prior to Crash Damaged Area Code: (Circle Up to Three)							ee)		
5		Direction: N		onding to Emergency? N			22 22	22	22	•	3		4	
		ssued)		gg, - <u></u>		Harmful Event	23]				Λ`	10 Undercarr	riage
				2: ChSec		Contributing C		1 24	24		9		5 11 Totaled	
⁶ 1	Violation	3: ChSec	Underride/Override Z5 Towed N 8 7 6											
	Please fill out for operator and all occupants involved Name (Last First Middle) Address				26 27 28 29 30 31 32 33 Seat Safety Airbag Airbag Airbag Airbag Feet Trap Injury Transp. Age/DOB Sex Pos. \$ystem Status Wintch Code Code Status Code Medical Facility							. 2		
	Operator	st Wildle)		See Above				99	4	99 0	0	10 1		- I
⁷ 1	Please Select C of the Followi		2 <u>1</u> #Occupant	s Non-Motorist A Typ	pe 1	4 Action	15 Loca	ation	16 Co	ondition	17	Ні	t/Run Mop	ed
	License # St MA DOB/Age				Reg#	Reg # 911FV2 Reg Type PAN					Reg	State_MA	_	
	Sex_M Lic. Class D 18 18 Lic. Restrictions 1 CDL				_	Veh Year 2012 Veh Make ACURA Veh Config.					20			
⁸ 1	Operator SUI	Operator SULLIVAN JOSEPH Endorsment				Owner (Same as operator)								_
1	Address 71 CEDAR LN					Last First Middle Address								_
	City WESTWOOD State MA Zip 02090				City State Zip								_	
	Insurance Company_ARBELLA					Vehicle Action Prior to Crash 10 Damaged Area Code: (Circle Up to Three)								ee)
	Vehicle Travel Direction: $\begin{tabular}{ c c c c c c c c c c c c c c c c c c c$					Event Sequence 2 22 22 22 2 3 4							.	
	Citation # (If Issued)					Most Harmful Event 2 23 10 Undercarriage 5 11 Totaled							rage	
	Violation 1: ChSec Violation 2: ChSec					Driver Contributing Code 19 24 24 8 7								
ſ	Violation 3: ChSec Violation 4: ChSec					Underride/Override Towed N						_		
	Pl Name (Last Fi		operator and all	occupants involved Address		Age/DOB	Sex	26 27 Seat Safety Pos. Syste	28 Airbag A m Status	29 Airbag Eje Switch Co	0 31 Trap de Code		33 ansp. Code Medical Faci	lity
	Operator/	Non-Motorist		See Above			-	99	4	99 0	0	10 1		
ľ														

	Direction 1 :	Vehicle 1 2	₹Vehicle 2	₽Pedestr	ian						
Crash Diagram:	ie: 🕕 🛚	2		→ ĝ							
361 W	ashington S	t. RS Ga	S			Crash <u>Did Not</u> Coash a Public Way:	Occur				
						Off-Street Parking	g Lot				
		Veh	icle #2			Garage					
	į		V	/ehicle #1		Mall/Shopping Ce	enter				
						Other Private Way	,				
					Ind	icate North by A	rrow				
				\triangle		Cate North by A	iiow				
Crash Narrative:											
Operator of vehicle #1 s	tated he was park	ed at RS gas	on 10/24/20	19 at 1500	hrs when Vel	nicle # 2 Back	ked into				
his vehicle, causing min											
had left the gas station. Operator #2 was contacted by me and stated he had been at the gas station and											
backed up close to vehic	le #1 but was una	ware that he	had made co	ontact with	vehicle #1.						
W itnesses: Name (Last, First, Middle)		Address			Phone	#	Statement				
Property Damage: Owner (Last, First, Middle)	Address		Phone #	34-Type	Description of Dam	aged Property					
Owner (Last, First, Middle)	Address		THORE #	эттуре	Description of Dam	aged i roperty					
Truck and Bus Information:	Registration #		(From V	Pehicle Section)			35				
Carrier Name						suing Authority Cod	е				
Address City St Zip											
US DOT #:	State Number		_ Issuing State	ICC #:		Interstate	36				
Cargo Body Type Code 37	Gross Vehicle Weight	38									
Trailer Reg #:	Reg Type	Reg State	Reg Year	Tra	iler Length						
Hazmat Information:		-		_							
Placard 40 Material 1 dig	it # 41 Material Na	me		Material 4 c	ligit #	_ Release code	42				
DANIEL NARDELLI			NE	EWTON POLICE DEPARTM		10/25/20)19				

ID/Badge #

Department

Signature

Precinct/Barracks

Date

Police Officer Name (Please Print)