
	Pol	ice Use Only		Com monweal	lth o	f Mass	ach	usett	S		RMV	V Docun	nent Number			
	Date of Crash 02/26/2020	Time of Crash 15:14 24HR	NEWTON	MIOTOI		icle Cra Report	sh	Number Vehicle		red Lat	eed Limi titude ngitude_		State Police Local Police MBTA Police Other:	XI D		
			RSECTION:		OCAT		>		N	от ат	INTI	ERSEC	CTION:			
						SOUTH	98	i	GRE	ENWOO	DD ST					
1	Route# Direction Name of Roadway/Street At				Route# Direction Address # Name of Roadway/Street								2			
						Feet NSEW of or exit Number										
	Route# Direction Name of Intersecting Roadway/Street Also at Intersection with					Feet NSEW of Route# Intersecting Roadway/Street										
² 2					-	Feet	N S E	W of	Kot	ite#	Intersec	ting Koac	iway/Street	4		
3	Route# Direc	Route# Direction Name of Intersecting Roadway/Street					Landmark									
	XVehicle1	_1_#Occupants	X Hit/Run	Moped Case N	lumber		2	00000019	92					╝		
	License#	License # St MA DOB/Age 18 18 19											State MA	_		
	Sex_M_ Lic.	Class	Lic. Restrictions	Endorsment REUBEN		ear_2004				A		Veh Co	nfig. 2			
4 1	Operator KO	RSUNSKY Last WHINDA (apt. 1	ARON First	REUBEN Middle		CHOWDHU La: 7 BEACH ST		SEEN	/IA First			Middle		- 3		
	Address St D			MA 7in 02468			KLLI				Stata	MA ,	zin 02458	-		
	City NEWTON State MA Zip 02468 Insurance Company ARBELLA MUTUAL					City NEWTON State MA Zip 02458 Vehicle Action Prior to Crash 11 21 Damaged Area Code: (Circle Up to Three)										
5	1	Direction: X		ding to Emergency? N			22 2	11	22	2	3		4			
	Citation # (If I	ssued)			Most E	Iarmful Event	1 2.	3		1 4	9	$\{ \cdot \}$	10 Undercarr 5 11 Totaled	riage		
6	Violation	1: ChSec	C Violation 2:	ChSec	Driver	Contributing C		1 24	24	8			6			
⁶ 1	Violation 3: ChSec Violation 4: ChSec					Underride/Override Towed N								\dashv		
	Please fill out for operator and all occupants involved Name (Last First Middle) Address				Age/DOB Sex Pos. System Status Switch Code Code Status Code Medical Facility							1				
	Operator			See Above				99	4	4 0	0	10 1				
								_								
7					1-				16		17			_		
1	Please Select C of the Followi	Vehicle	e# Occupants	Non-Motorist A Type) I	Action	Loc	cation	16 Co	ondition	17	Hit	t/Run Mop	ed		
	License#StDOB/Age				Reg#_	Reg # Reg Type Reg State							_			
	Sex Lic. Class 18 18 Lic. Restrictions 19 CDL Endorsment					/eh Year Veh Make Veh Config. 20										
8 1	Operator					Owner Last First Middle										
	Address					Address										
	City State Zip Insurance Company					City State Zip Vehicle Action Prior to Crash Damaged Area Code: (Circle Up to Three)										
	Vehicle Travel Direction: NSEW Responding to Emergency?					Event Sequence 22 22 22 22 3 4										
	Citation # (If Issued)					Most Harmful Event 23 10 Undercarriage 5 11 Totaled								riage		
	Violation 1: ChSec Violation 2: ChSec					Driver Contributing Code 24 24										
	Violation 3: ChSec Violation 4: ChSec					Underride/Override										
	Pl Name (Last F		operator and all oc	ccupants involved Address		Age/DOB	Sex	26 Seat Safe Pos. Sys	7 28 ty Airbag tem Status	29 Airbag Eje Switch Co	0 31 ct Trap ode Code	Injury [Tra	nsp. ode Medical Faci	lity		
	Operator/	Non-Motorist		See Above												



Crash Narrative:

On Wednesday 2/26/20 while assigned to marked unit n499 I was dispatched to the front of 98 Greenwood Street for a report of a past motor vehicle hit and run.

Upon arrival I spoke with KORSUNSKY Aron, who states at approximately 9:00am this morning he parked his vehicle (Ma Reg 28CS77) in front of 98 Greenwood Street. When he came back to his vehicle at approximately 3:00pm KORSUNSKY states he observed his drivers side mirror to be damaged.

Upon my arrival I observed the drivers side mirror damaged to the point it is inoperable. I also observed damage to the drivers side fender that was being held together by duct tape indicating to me it was damage from a prior crash. I asked KORSUNSKY about the fender damage and he confirmed it was old damage, He further stated to me the damage to the mirror was the only damage from today's incident.

(Continued on next page)

Witnesses:										
Name (Last, First, Middle)	Address			Phone #		Statement				
Property Damage:		•								
Owner (Last, First, Middle)		Phone #	34-Type	Desc	ription of Damaged P	roperty				
Truck and Bus Information: Carrier Name	Registration #			, i		Carrier Issuing A	authority Code	35		
Address			City			St	Zip			
US DOT #:			_ Issuing State	In	iterstate	36				
Cargo Body Type Code Gross Vehicle Weight 38										
Trailer Reg #:	Reg Type	Reg State	Reg Year	Tr	ailer L					
Hazmat Information:										
Placard 40 Material 1 digit #	# 41 Material Na	me		Material 4	digit #	Rel	ease code	42		

-	Direction	1 Vehicle	1 <u>2</u> #Veh	icie 2	₹ Pedestr	ian		
Crash Diagram:	ie: →□	1 -	2	→	· P			
	_		. —				If Crash Did Not (on a Public Way: Off-Street Parking Garage Mall/Shopping Co	g Lot enter
Crash Narrative:								
While on scene I looked a	t 98 Greenwood	Street to	o see if t	here was	any surv	eillen	ce cameras with nega	tive
results.								
Witnesses:								
Name (Last, First, Middle)		Address					Phone #	Statement
Property Damage:								
Owner (Last, First, Middle)	Address		Pho	ne #	34-Type	Descrip	tion of Damaged Property	
Truck and Bus Information:	Registration # _			(From Vehi	cle Section)			
Carrier Name						Carrier Issuing Authority Code		
Address			City				Ct Zin	
			•					36
US DOT #:	_ State Number		Issu	ing State	ICC #:_		Interstate	30
Cargo Body Type Code 37 Gr	oss Vehicle Weight	38						
 Trailer Reg #:	Reg Type	Reg St	ate	Reg Year	T⊷	ailer I enc	oth 39	
Hazmat Information:	reg Type	Neg St		_ Nog i cai	118	and LUIL	p	
40	41							42
Placard Material 1 digit	# Material	Name			Material 4	digit#	Release code	
ALAN JR RICHARD SOLOMAN.				NEWTO	N POLICE DEPARTS		02/26/20	020

ID/Badge #

Department

Signature

Precinct/Barracks

Date

Police Officer Name (Please Print)