	Polic	ce Use Only		Comm	ıonweal	lth o	f Massa	achu	iset	ts					nt Number	
	Date of Crash 08/06/2020	Time of Crash 10:13	h City/1	Γown			icle Cra	sh	Numb Vehic			Speed Li Latitude		SI	State Police Local Police MBTA Police	
L	00/00/2020	24HR					Report		2	0		Longitud			Other:	ш
Ļ		AT INTE	RSECTION	:	< L	LOCAT	ION	>		N	OT A	AT IN	TERS	ECT	TON:	
							SOUTH	457	7	WA	LNUT	ST				
1	Route# Direct	tion	Name	of Roadway/Street	t		Route# Direction	on Ad	ldress #			Name o	f Roady	vay/Str	eet	
\dashv				At			Feet 1	N S E	W of			. • _	- or			
-	Route# Direct	tion	Name of Intersec	ting Roadway/Stre	eet	— [-				M	le Mark	cer			Exit Number	
1			Also at Int	tersection with		-	Feet I	N S E	W of	Ro	ute#	Inter	secting l	Roadw:	ay/Street	-
7						-	Feet [N S E	W of						-9	
⋠	Route# Direct	tion	Name of Inter	secting Roadway/S	Street								Landma	rk		
	XVehicle1	#Occupants	s Hit/Ru	n Mope	ed Case N	Number		20	0000004	29						1
7	License#		St ¹	MA DOB/Age		Reg#N	M2940A			Red	Type_	MVN	ŀ	Reg Sta	nte_MA	
	Sex_M Lic. C	Tlass B	18 Lic. Restricti	19	DL T	-	ar_2007	Vel	n Make	-				Config	20	_
	Operator DAC		MATTHEW	V En	dorsment		CITY OF NEV			V				,	5.	
	Address 1 LISA	Last A LN	First	1	Middle		S 110 CRAFTS	t		Firs	t		М	iddle		_
- 1	City WALTHA		-	State MA Zip C	02452		EWTON					St	ate MA	7in	02458	
	,		TY OF NEWTON	-		,	Action Prior to	Crash		21				-	cle Up to Thre	ee)
_	Vehicle Travel			esponding to Emer	rgency? N			22 22	2 22	22	0 _		3	4	-	
	Citation # (If Is			sponding to Eme	igency:		requence 1	23					\square		10 Undercarri	riage
				on 2: ChSe	90		[armful Event	1	1 24	24	1	-	9	5	11 Totaled	
٦				on 4: ChSe			Contributing Co	25		wed N	8		7	6		
+				cupants involved		Undern	ide/Override [П	26 Z Seat Safe		29	30 Eject Tra	31 32 p Injury	33 Transp	1	-
\vdash	Name (Last Firs				Address		Age/DOB	Sex 1	Pos. Syst		Switch	Code Cod		Code	Medical Facili	ity
-	Operator				Above				1	4	99	0 0	10	1		
-														_		
L																
	Please Select O		le2 1_#Occupa	ants Non-M	lotorist A Type	e 14	4 Action 1	5 Loca	ation	16 C	onditio	n 1	7	Hit/R	un Mop	ed
_	of the Followir	ng:														
- 1	License # St MA DOB/Age				=======================================	-	eg # 491DH5 Reg Type PAN Reg State MA						MA 20	-		
_	Sex_F Lic. Class D Lic. Restrictions B CDL						Veh Year 2019 Veh Make SUBARU Veh Config. 1									
- 1	Operator Last NAOMI B					Owner LICHTIN HAROLD Last First Middle								-		
- 1	Address 53 PINE CREST RD				Address 53 PINE CREST RD								-			
1	City NEWTON State MA Zip 02459)2459	City NEWTON State MA Zip 02459								-		
1	Insurance Company SAFETY				Vehicle Action Prior to Crash 2 21 Damaged Area Code: (Circle Up to Three)								ee)			
1	Vehicle Travel Direction: N K E W Responding to Emergency? N				ergency?N	Event Sequence 1 22 22 22 22 2 3 4										
1	Citation # (If Issued)				Most Harmful Event 1 23 10 Undercarriage 5 11 Totaled								nage			
	Violation 1: ChSec Violation 2: ChSec				Driver Contributing Code 97 24 24 24 7 7 8											
	Violation	n 3: ChS	Sec Violat	tion 4: ChS	Sec	Underri	ide/Override	25	Tow	ed N	8		/			
	Ple Name (Last Fir		r operator and a	all occupants inv	volved Address		Age/DOB		26 Seat Safe Pos. Sy	27 28 ety Airbag stem Status	29 Airbag Switch	30 Tra		Transp).	ilitv
		Non-Motorist			Above				1	4		0 0	10	1	curcui racii	
r																
									\top					T		
-																

	Ulrection 1 = venicle 1 2 = venicle 2	Pedestrian Pedestrian
Crash Diagram:	ie: → 1 → 2	→ Ŷ
		If Crash <u>Did Not</u> Occur on a Public Way:
		☐ Off-Street Parking Lot
		☐ Garage
		☐ Mall/Shopping Center
	N. N	☐ Other Private Way
	ANOT TO SCALE 457 WALNUT ST	Indicate North by Arrow

Crash Narrative:

(Continued on next page)

City of Newton DPW employee Matthew Dagostino stated that on 08/06/2020 at 10:13 hours he was driving a 2007 International 7400 dump truck south bound on Walnut St in the area of number 457. Walnut St is a public way in the city of Newton. Dagostino stated that the truck was equipped with a sander and it's gross weight was appropriately 26,000 lbs. Dagostino stated that his speed was approximately 25 MPH as he drove past 457 Walnut St. Dagostino stated that a vehicle that was travailing south bound in front of his truck MA reg 491DH5 a 2019 Subaru Impreza stopped short. Dagostino stated that the Subaru stopped to let a pedestrian cross the street. Dagostino stated that when the Subaru stopped abruptly it caught him off guard because there was no marked crosswalk in the area. Dagostino stated when the Subaru stopped short he applied the breaks to his truck and had to turn to the left in an attempt to avoid a crash. Dagostino stated that his

Witnesses:

Name (Last, First, Middle)

Address

Phone # Statement

Property Damage:

Owner (Last, First, Middle)

Address

Phone # 34-Type Description of Damaged Property

Truck and Bus Information: Registration #	(From Vehicle Section)
Carrier Name	Carrier Issuing Authority Code
Address	City St Zip
US DOT #:State Number	Issuing State ICC #: Interstate 36
Cargo Body Type Code Gross Vehicle Weight 38	39
Trailer Reg #: Reg Type Reg State _	Reg Year Trailer Length
Hazmat Information:	
Placard 40 Material 1 digit # 41 Material Name	Material 4 digit # Release code 42

MICHAEL A MCSWEENEY NEWTON POLICE DEPARTN 08/06/2020
Police Officer Name (Please Print) Signature ID/Badge # Department Precinct/Barracks Date

	Direction 1	∃ Vehicle 1 2	2_ ‡ Vehicle ∠	₹ Pedestri	an	
Crash Diagram:	ie: → 1	2	2	→ §		
						<u>Did Not</u> Occur Dlic Way:
					—— ☐ Off-Se	treet Parking Lot
					☐ Garag	re l
						Shopping Center
	i			+		11 0
					☐ Otner	Private Way
					Indicate	North by Arrow
			 	 	(
Crash Narrative:						
truck's front passenger s	side bumper made	contact with	the Subaru	ı's rear driv	ver's side bumper	and tail light.
Dagostino's truck had sma	ill scrapes to th	ne front pass	senger side	bumper. Neth	ner operator state	d that they were
injured and the vehicles	were not towed	d.Lev's vehic	ele had dama	ige to the re	ear driver's side	bumper and tail
light . I took photo's of	both vehicle a	and this disk	was tuned	over to the	NPD's It bureau f	or downloading.
Operator of vehicle two N	laomi Lev stated	that she was	driving so	outh bound or	Walnut St when s	he said she was
attempting to turn left i	nto Berwick Rd a	and stopped t	o let a pec	lestrian acro	oss over Walnut St	. It should be
noted that Berwick Rd is	approximately 1/	/2 of a mile	south of wh	ere the cras	sh occurred. Lev s	tated that she
did stop her vehicle to 1	et a pedestrian	across just	prior to th	ne crash.		
Witnesses:	_					
Name (Last, First, Middle)		Address			Phone #	Statement
Property Damage:						
Owner (Last, First, Middle)	Address		Phone #	34-Type	Description of Damaged P	roperty
Truck and Bus Information:	Registration #		(From	Vehicle Section)		
Carrier Name				,	Carrier Issuing A	authority Code 35
Address			City		St	Zip
US DOT #:	State Number		Issuing State	ICC #:	In	iterstate 36
Cargo Body Type Code 37 Gr	ross Vehicle Weight	38				
Trailer Reg #:	Reg Type	Reg State	Reg Ye	ar Trai	iler Length 39	
Trailer Reg #: Hazmat Information:	Reg Type	Reg State	Reg Ye	ar Trai		