

Police Use Only			Commonwealth of Massachusetts				RMV Document Number					
Date of Crash 08/10/2020	Time of Crash 13:36 24HR	City/Town NEWTON	Motor Vehicle Crash Police Report		Number Vehicles 2	Number Injured 0	Speed Limit 25 Latitude _____ Longitude _____	State Police <input type="checkbox"/> Local Police <input checked="" type="checkbox"/> MBTA Police <input type="checkbox"/> Other: <input type="checkbox"/>				
AT INTERSECTION:			< LOCATION >		NOT AT INTERSECTION:							
<div>11Route# Direction Name of Roadway/Street At</div> <div>21Route# Direction Name of Intersecting Roadway/Street Also at Intersection with</div> <div>3Route# Direction Name of Intersecting Roadway/Street</div>			<div>29NORTH 19 WOODBINE ST</div> <div>210Route# Direction Address # Name of Roadway/Street</div> <div>Feet N S E W of _____ • _____ or _____ Mile Marker Exit Number</div> <div>11Feet N S E W of _____ Route# Intersecting Roadway/Street</div> <div>4Feet N S E W of _____ Landmark</div>									
<input checked="" type="checkbox"/> Vehicle 1 1 #Occupants			<input type="checkbox"/> Hit/Run		<input type="checkbox"/> Moped		Case Number 2000000443					
License # --- St RI DOB/Age --- Sex M Lic. Class B 18 18 Lic. Restrictions 1 19 CDL T Operator VELASCO AGUSTIN PINOL Address 189 HAROLD ST City PROVIDENCE State RI Zip 02908 Insurance Company ACE AMRICAN			Reg # N45652 Reg Type CON Reg State MA Veh Year 2009 Veh Make AUTO Veh Config. 13 20 Owner WASTE MANAGEMEN Address 100 HILL ST City NORTON State MA Zip 02766 Vehicle Action Prior to Crash 1 21 Event Sequence 2 22 22 22 22 2 Most Harmful Event 2 23 Driver Contributing Code 19 24 24 Underride/Override 25 Towed N									
Vehicle Travel Direction: <input checked="" type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W Responding to Emergency? N Citation # (If Issued) T2015997 Violation 1: Ch A7/17 Sec Violation 2: Ch Sec Violation 3: Ch Sec Violation 4: Ch Sec			<div>12Diagram: 10 Undercarriage, 11 Totaled</div>									
Please fill out for operator and all occupants involved			13									
Name (Last First Middle) Address Age/DOB Sex Seat Pos. Safety System Airbag Status Airbag Switch Eject Code Trap Code Injury Status Transp. Code Medical Facility			2									
Operator See Above												
Please Select One of the Following: <input checked="" type="checkbox"/> Vehicle 2 1 #Occupants			<input type="checkbox"/> Non-Motorist A Type 14		Action 15		Location 16		Condition 17		<input type="checkbox"/> Hit/Run <input type="checkbox"/> Moped	
License # --- St MA DOB/Age --- Sex F Lic. Class D 18 18 Lic. Restrictions 1 19 CDL Operator BROWN MAURA NOLAN Address 1160 BEACON ST (apt. 301) City BROOKLINE State MA Zip 02446 Insurance Company COMMERCE			Reg # 5GD698 Reg Type PAN Reg State MA Veh Year 2017 Veh Make RANGE ROVER Veh Config. 2 20 Owner (Same as operator) Address City State Zip Vehicle Action Prior to Crash 11 21 Event Sequence 1 22 22 22 22 2 Most Harmful Event 1 23 Driver Contributing Code 1 24 24 Underride/Override 25 Towed N									
Vehicle Travel Direction: <input checked="" type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W Responding to Emergency? N Citation # (If Issued) Violation 1: Ch Sec Violation 2: Ch Sec Violation 3: Ch Sec Violation 4: Ch Sec			<div>13Diagram: 10 Undercarriage, 11 Totaled</div>									
Please fill out for operator and all occupants involved			13									
Name (Last First Middle) Address Age/DOB Sex Seat Pos. Safety System Airbag Status Airbag Switch Eject Code Trap Code Injury Status Transp. Code Medical Facility			10 1									
Operator/Non-Motorist See Above												

→ Direction    1 = Vehicle 1    2 = Vehicle 2    Pedestrian

ie: → 1    → 2    → Pedestrian

**Crash Diagram:**

WOODBINE ST

Unit 1

Unit 2

19 WOODBINE ST

Indicate North by Arrow

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

**Crash Narrative:**

Operator of vehicle one, Agustine Velasco stated that on 08/10/2020 at 13:36 hours he was driving a city of Newton contacted Waste Management trash truck ( 2009 Atuo Xpedit ) northbound on Woodbine St.

Woodbine St is a pubic way in the city of Newton. Velasco stated that as his vehicle passed a parked unoccupied northbound facing vehicle ( 2017 Rage Rover MA reg 5GD698 ) in front of 19 Woodbine St the mechanical arm that picks ups trash barrels was not stored in the fully closed position. Velasco stated that the mechanical arm's clamp struck the driver's side rear door and lower quarter panel of the Range Rover causing extensive damage. The truck's arm clamp was broken off in the crash. Owner of vehicle two Maura Brown stated her vehicle was parked unoccupied facing north in front of 19 Wood brine St prior to the crash. Neither vehicle was towed . Velasco stated that hen was not injured in the crash. I took photos of both

(Continued on next page)

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate

Cargo Body Type Code  Gross Vehicle Weight

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code

MICHAEL A MCSWEENEY      NEWTON POLICE DEPARTM      08/10/2020

Police Officer Name (Please Print)      Signature      ID/Badge #      Department      Precinct/Barracks      Date

CDP1 11 -24-00

