

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 → Pedestrian

Crash Diagram:

BRACKETT RD. WAVERLY AVE UT #1 NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

On 09/30/2020 I responded to the area of Waverley Ave and Brackett Rd for a single vehicle motor vehicle crash involving a utility pole. Both Waverley Ave and Brackett Rd are public ways in the City of Newton.

Vehicle 1 described as a 2011 Kenworth commercial box truck (RI Con Reg 80859). Vehicle 1 was traveling southbound on Waverley Ave when it struck overhanging utility wires (Eversource Pole #44) located over the roadway near the intersection of Brackett Rd. As a result of the impact Vehicle 1 sustained major damage to the roof of the cargo area. The force of the impact caused the utility pole #44 to break in half. It should be noted that at the time of the crash the weather was steady rain with high winds.

No injuries were reported on scene.

The operator of Vehicle 1 stated that he was traveling southbound on Waverly Ave and did not see the power

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property
, EVERSOURCE,	,		4	POLE#44

Truck and Bus Information:

Registration # 80859 (From Vehicle Section)

Carrier Name CEI TRANSPORTATION Carrier Issuing Authority Code 35

Address 22E LARK INDUSTRIAL PARKWAY City GREENVILLE St _____ Zip 02828

US DOT #: 1223129 State Number _____ Issuing State RHODE ICC #: _____ Interstate 1 36

Cargo Body Type Code 97 37 Gross Vehicle Weight 2 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

JASON M. SCHLEGEL NEWTON POLICE DEPT 09/30/2020

Police Officer Name (Please Print) Signature ID/Badge # Department Precinct/Barracks Date

CDP1 11 -24:00

Crash Narrative:
lines until it was too late.
After further investigation it was determined that a tree(private) located on Brackett Rd had come down
due to the high winds and landed on power lines. These power lines were also attached to utility pole #44.
The force caused the power lines from utility pole #44 to sag over Waverley Ave. As result Vehicle 1 did not
have enough clearance under the power lines.
Vehicle 1 was towed from the scene by Tody's Towing. Towed MV inventory completed.
Due to the live wires in the roadway, Newton Fire responded and secured the scene.
Eversource was also notified and responded to the scene.
Pictures were taken and submitted to the IT Bureau.

Property Damage:				
Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

JASON M. SCHLEGEL			NEWTON POLICE DEPARTA		09/30/2020
Police Officer Name (Please Print)	Signature	ID/Badge #	Department	Precinct/Barracks	Date
CDP1 11 :24:00					