



→ Direction    1 Vehicle 1    2 Vehicle 2    Pedestrian

ie: → 1    → 2    →

**Crash Diagram:**

169 River St

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

**Crash Narrative:**

Operator states that she was driving westbound on River St when she felt her vehicle hit something in the road. She did not see anything, but completely lost control of MA reg 1LFH86. The vehicle ended up hitting a utility pole and sustained heavy damage/airbag deployment.

Upon inspecting the scene, a rotor was located on River St near Auburndale Ave. It appears that the vehicle's right front balljoint snapped and caused severe mechanical failure, in turn causing the operator to lose control.

Medics documented a patient refusal and Tody's towed the vehicle to their lot. Eversource was notified to check the integrity of pole #25 in front of 169 River St.

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate

Cargo Body Type Code  Gross Vehicle Weight

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code