

→ Direction 1 Vehicle 1 2 Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

Beacon St

Access Rd in Pkg Lot

916 Walnut Loading Dock

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

○

Crash Narrative:

Mv#1 (tractor trailer) operator stated he had a clear access road in the parking lot as he was backing to make a delivery into the Whole Foods loading dock. #1 further stated before he backed up, he observed Mv#2 off to an adjacent side corner of the parking lot, which left the access road clear leading to the loading dock. #1 stated at that time while he was backing, #2 attempted to pass his trailer on the right. A collision occurred with the passenger side rear trailer and the driver's side front of #2.

#2 operator stated he was attempting to exit the parking lot by the access road leading out to Beacon St. #2 further stated he observed the trailer backing up, at which time he stated he came to a complete stop and was honking his horn to alert #1. #2 stated at that time, #1 did not stop and backed into his driver's side front end. #2 sustained moderate damage. #1 sustained no damage to the rear trailer.

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

→ Direction 1 Vehicle 1 2 Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:



If Crash Did Not Occur
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



Crash Narrative:

Observations of Mv positioning on arrival was: the trailer was almost fully in the center of the access road leaving only about a 3 foot opening from the curb on its right. Mv#2 was in the far right lane of the access road. Although #2 reported he came to a complete stop prior to the collision, it appeared #2 intended to pass and approached too closely to the rear of the trailer to leave enough safe distance between both Mvs.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

ADAM D GABRIEL

25117

NEWTON POLICE DEPART

02/15/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date