

Police Use Only			Commonwealth of Massachusetts				RMV Document Number					
Date of Crash 02/22/2021	Time of Crash 08:49 24HR	City/Town NEWTON	Motor Vehicle Crash Police Report			Number Vehicles 2	Number Injured 0	Speed Limit 5 Latitude Longitude	State Police <input type="checkbox"/> Local Police <input checked="" type="checkbox"/> MBTA Police <input type="checkbox"/> Other: <input type="checkbox"/>			
AT INTERSECTION:			< LOCATION >		NOT AT INTERSECTION:							
<div>11Route# Direction Name of Roadway/Street At</div> <div>22Route# Direction Name of Intersecting Roadway/Street Also at Intersection with</div> <div>3Route# Direction Name of Intersecting Roadway/Street</div>			<div>29WEST 33 AUSTIN ST</div> <div>10Route# Direction Address # Name of Roadway/Street</div> <div>Feet N S E W of or Mile Marker Exit Number</div> <div>Feet N S E W of Route# Intersecting Roadway/Street</div> <div>Feet N S E W of Landmark</div>									
<input checked="" type="checkbox"/> Vehicle 1 0 #Occupants			<input checked="" type="checkbox"/> Hit/Run		<input type="checkbox"/> Moped		Case Number 2100000142					
License # St DOB/Age Sex Lic. Class 18 18 Lic. Restrictions 19 CDL Endorsment			Reg # 6CS197 Reg Type PAN Reg State MA Veh Year 2017 Veh Make JEEP Veh Config. 2 20									
Operator Last First Middle Address City State Zip Insurance Company USAA CASUALTY			Owner CARRILLO DANIEL Address 24 WISWALL ST City NEWTON State MA Zip 02465									
Vehicle Travel Direction: <input checked="" type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W Responding to Emergency? N			Vehicle Action Prior to Crash 11 21 Damaged Area Code: (Circle Up to Three)									
Citation # (If Issued)			Event Sequence 1 22 22 22 22 2 Most Harmful Event 1 23									
Violation 1: Ch Sec Violation 2: Ch Sec			Driver Contributing Code 1 24 24									
Violation 3: Ch Sec Violation 4: Ch Sec			Underride/Override 25 Towed N									
Please fill out for operator and all occupants involved			26 27 28 29 30 31 32 33 Seat Pos. Safety Airbag Airbag Eject Trap Injury Transp. System Status Switch Code Code Status Code Medical Facility									
Operator See Above												
Please Select One of the Following: <input checked="" type="checkbox"/> Vehicle 2 1 #Occupants			<input type="checkbox"/> Non-Motorist A Type 14		Action 15		Location 16		Condition 17		<input checked="" type="checkbox"/> Hit/Run <input type="checkbox"/> Moped	
License # --- St MA DOB/Age ---			Reg # 1NTE29 Reg Type PAN Reg State MA									
Sex F Lic. Class D 18 18 Lic. Restrictions B 19 CDL Endorsment			Veh Year 2019 Veh Make TOYT Veh Config. 2 20									
Operator RUSSO MELINDA Last First Middle			Owner (Same as operator) Last First Middle									
Address 55 REAGAN RD			Address									
City DRACUT State MA Zip 01826			City State Zip									
Insurance Company COMMERCE INS			Vehicle Action Prior to Crash 1 21									
Vehicle Travel Direction: <input checked="" type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W Responding to Emergency? N			Damaged Area Code: (Circle Up to Three)									
Citation # (If Issued) T1446762			Event Sequence 2 22 22 22 22 2									
Violation 1: Ch 19/75 Sec Violation 2: Ch Sec			Most Harmful Event 2 23									
Violation 3: Ch Sec Violation 4: Ch Sec			Driver Contributing Code 97 24 24									
			Underride/Override 25 Towed N									
Please fill out for operator and all occupants involved			26 27 28 29 30 31 32 33 Seat Pos. Safety Airbag Airbag Eject Trap Injury Transp. System Status Switch Code Code Status Code Medical Facility									
Operator/Non-Motorist See Above			99 4 99 0 0 10 1 N/A									

→ Direction 1 Vehicle 1 2 Vehicle 2 Pedestrian

Crash Diagram:

ie: → 1 → 2 →



If Crash Did Not Occur
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



Crash Narrative:

It is unclear at this time who was operating MV2 (MA# 1NTE29).

Dracut PD was contacted about the registered owner and I was able to get a phone number. However, the number was to a business she hasn't worked at in five years.

Traffic Bureau update (Officer Gaudet): On Monday, February 22, 2021 I was able to make contact with the registered owner of MV2, Ms. Melinda Russo (S29162725). Ms. Russo stated that she was operating her white 2019 Toyota Highlander (MA: 1NTE29) in the Austin Street municipal parking lot this morning. Ms. Russo stated she was backing out of a parking spot when she observed her passenger side mirror collapse in. Ms. Russo stated after she exited the parking spot she pulled her vehicle over and observed no

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

KEVIN DURICKAS

NEWTON POLICE DEPT.

02/22/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date

→ Direction 1 Vehicle 1 2 Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:



If Crash Did Not Occur
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



Crash Narrative:

damage to the passenger door mirror area. Ms. Russo stated she fixed her mirror and then left the area. Ms. Russo stated she did not think there would be damage to any other vehicle because she did not have damage on her vehicle.

Ms. Russo was advised that if she believes she was involved in a crash, she should make every effort to contact the owner of the other vehicle. Ms. Russo was also advised she can contact the police department for assistance. Ms. Russo will be mailed Massachusetts Uniform Citation T1446762 for Newton City Ordinance Chapter 19, Section 75 (Fail to Use Care). Austin Street is a public way maintained by the City of Newton.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

KEVIN DURICKAS

NEWTON POLICE DEPART

02/22/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date