

**Crash Narrative:**

ON 4-2-21 AT APPROX. 1419HRS. WHILE WORKING N492 I TOOK A REPORT FOR MOTOR VEHICLE ACCIDENT HIT AND RUN. UPON ARRIVAL AT THE INTERSECTION OF WALNUT AND BEACONST. I SPOKE TO THE OPERATOR OF VEHICLE #1. DRIVER STATES SHE WAS TRAVELING N-BOUND ON WALNUT ST. STOPPED AT THE RED LIGHT. SHE NOTICED VEHICLE #2 WAS TRYING TO BACK OUT OF HER DRIVEWAY. DRIVER STATES SHE MOVED UP IN THE TRAFFIC LANE SO VEHICLE #2 COULD BACK OUT. SHE STATES WHILE BACKING VEHICLE #2 HIT HER VEHICLE. AS SHE PULLED OVER TO EXCHANGE INFORMATION VEHICLE #2 SPED AWAY. VEHICLE #1 STATES SHE HAS MINOR DAMAGE TO HER LEFT REAR TIRE. I ATTEMPTED TO CONTACT VEHICLE #2 BY PHONE AND LEFT A VOICEMAIL. I HAVE NOT HEARD BACK FROM HER SINCE THE WRITING OF THIS REPORT. VEHICLE #1 REPORTED NO INJURIES AND WAS ADVISED TO CONTACT HER INSURANCE COMPANY. CLEARED WITHOUT FURTHER INCIDENT.

(Continued on next page)

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_


US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate

Cargo Body Type Code  Gross Vehicle Weight


Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code

→ Direction  1 Vehicle 1  2 Vehicle 2  Pedestrian

**Crash Diagram:**



If Crash Did Not Occur on a Public Way:

Off-Street Parking Lot


Garage

Mall/Shopping Center

Other Private Way

---

Indicate North by Arrow



**Crash Narrative:**

Traffic Bureau Update (Officer Gaudet): On Monday, April 5, 2021, I attempted to make contact with the registered owner of MV2 (Ms. Sarah Bonfanti) with a negative result. A "Hit and Run" inquiry was mailed to Ms. Bonfanti's listed address.

---



---



---



---



---



---



---



---

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_ Interstate

Cargo Body Type Code  Gross Vehicle Weight

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code