
	Poli	ice Use Only		Commonwea	alth o	of Mass	achu	setts	5		RM	V Docun	ment Number		
	Date of Crash 04/12/2021	Time of Crash 11:15 24HR	NEWTON	MIOTOI		icle Cra Report	sh [Number Vehicles 2		ed Lat	ed Limi itude _ igitude_		State Police Local Police MBTA Police Other:	XI D	
			RSECTION:		LOCA		>						CTION:	\neg \vdash	
	EAST	Γ CENTR	RE AVE											2	
1 1	Route# Direc			Roadway/Street		Route# Direction	on Ad	dress #		Na	ame of I	Roadway	/Street		
	At CENTRE ST				Feet NSEW of or									$ \frac{2}{}$	
	Route# Direction Name of Intersecting Roadway/Street					Mile Marker Exit Number									
	Also at Intersection with					Feet N S E W of Route# Intersecting Roadway/Street									
² 3	Route# Direc	tion	Name of Intersec	eting Roadway/Street		Feet	N S E	W of						3	
3	Route# Direction Name of Intersecting Roadway/Street				Landmark										
	XVehicle1	#Occupants	Hit/Run	Moped Case	Number		21	.00000259)						
	License# St NH DOB/Age				Reg # V67123 Reg Type CON Reg State MA										
	Sex F Lic. Class D 18 18 Lic. Restrictions 9 19 CDL Endorsment					Veh Year 2020 Veh Make HINO Veh Config. 6 20									
⁴ 3	Operator SPR		AMANDA First	Middle		THE REST S	TOP LLO	2	First			Middle		- 1	
<u> </u>	Address 55 SOUTH MAIN ST			Address PO BOX 57									-		
	City SEABROOK State NH Zip 03874				City_I	PSWICH							Zip <u>Q01938</u>	_	
	Insurance Company COMMERCE					Vehicle Action Prior to Crash Damaged Area Code: (Circle Up to Three)									
5	Vehicle Travel Direction: NXEW Responding to Emergency? N Event Sequence 122 22 22 22 23 4							١							
	Citation # (If I	· · · · · · · · · · · · · · · · · · ·			Most I	Harmful Event	1 23		24	—	9	<u> </u>	10 Undercarr 5 11 Totaled	nage	
6	Violation	Violation 1: ChSec Violation 2: ChSec Driver Contributing Code 9 24 24													
Violation 3: ChSec Violation 4: ChSec Underride/Override								1 22 1							
	Please fill out for operator and all occupants involved Name (Last First Middle) Address				Age/DOB Sex 26 27 28 29 30 31 32 33 Safety Airbag Airbag Airbag Eject Trap Injury Transp. Code Code Status Code Medical Facility							ity 1			
	Operator			See Above				1	4 9	9 0	0	10 1	NONE		
⁷ 3	Please Select C of the Followi	IX Vehicle	2 <u>1</u> #Occupant	s Non-Motorist A Tyj	pe 1	Action	15 Loca	ition	16 Cor	ndition	17	Hi	t/Run Mop	oed	
	License # St MA DOB/Age					Reg # 9TM360 Reg Type PAN Reg State MA								_	
	Sex F Lic. Class D 18 18 Lic. Restrictions 9 19 CDL				Veh Year 2017 Veh Make PRIUS Veh Config. 1										
8 4	Operator ESTRADA BINNIE Endorsment					Owner (Same as operator)									
T	Address 17 COPLEY ST					Last First Middle Address									
	City NEWTON State MA Zip 02458					CityStateZip									
	Insurance Company_GEICO					Vehicle Action Prior to Crash 1 Damaged Area Code: (Circle Up to Three)									
	Vehicle Travel Direction: NSWW Responding to Emergency?N					Event Sequence 1 22 22 22 22 3 4									
	Citation # (If Issued) Most Harmful Event 1 23							10 Undercarriage 5 11 Totaled							
	Violatio	Violation 1: Ch Sec Violation 2: Ch Sec Driver Contributing Code 1 24 24 Violation 3: Ch Sec Violation 4: Ch Sec Underride/Override 25 Towed N Towed N													
	Violatio														
	Pl Name (Last Fi		operator and all	occupants involved		Age/DOB		26 27 Seat Safety Pos. System	28 Airbag A m Status S	29 Ejec witch Co) 31 Trap de Code	Injury Tra	33 ansp. code Medical Facil	ility	
		Non-Motorist		See Above				· 1		9 0	0	10 1	NONE		
						+								\dashv	



	→ Direction 1 = Vehicle 1	2 =Vehicle 2	₽Pedestrian	
Crash Diagram:	ie: → □ →	2	▶ ĝ	
				If Crash <u>Did Not</u> Occur on a Public Way:
				☐ Off-Street Parking Lot
				☐ Garage
				☐ Mall/Shopping Center
				Other Private Way
				Indicate North by Arrow
		_		
		i i	į	
Crash Narrative:		,		_
Vehicle #2 was a blue Pr	ius station wagon, MA reg	9TM360 that sust	ained heavy rear	quarter drivers side
damage.				
The operator/owner ident	ified as Binnie Estrada.			
She stated that she was	stopped for the traffic 1:	ight on Centre Av	e at Centre St i	n the second lane. She
ndicated that she did s	ee vehicle #2 with its ri	ght turn signal	on but the truck	was to her left in the
third lane. She did wait	at first to yield to the	truck to turn ri	ght in front of	ner but when it didn't go
she began to go straight	ahead. The truck then be	gan to make its r	ight turn simul	taneously which led to the
crash.				
Operator #2 later said s	he never saw any funeral p	procession in the	right turn only	lane.
W itnesses:				
Name (Last, First, Middle)	Address			Phone # Statemen
Property Damage:				
Owner (Last, First, Middle)	Address	Phone #	34-Type Description	n of Damaged Property
Truck and Bus Information:	Registration #	(From Vo	hicle Section)	
Carrier Name			,	Carrier Issuing Authority Code
Address		City		St Zip
US DOT #:	State Number	Issuing State	ICC #:	Interstate 36
Cargo Body Type Code 37	Gross Vehicle Weight 38			
Trailer Reg #:	Reg Type Reg Stat	te Reg Year_	Trailer Length	39
Hazmat Information:				
Placard 40 Material 1 dig	it # Material Name		Material 4 digit #	Release code 42
THOMAS J MCCARTHY		NFW	TON POLICE DEPARTN	04/12/2021
Police Officer Name (Please Print)	Signature			ecinct/Barracks Date