

[illegible]

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

STAR MARKET

COMMONWEALTH AVE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

I responded to 2040 Commonwealth Ave for a report of two car MVA. I arrived on location and the two involved MV's pulled into the parking lot of the Star Market. V1; MA Reg 66LS55, 2016 Volvo/Stwag color gray, operated by Hamar, Benjamin MA OLNS70134803. V1 traveling southbound on Commonwealth Ave collided with V2. V2; MA Reg 294F30, 2020 Jeep/utl color white, operated by Xerras, Madeline MA OLN SA0790468. V2 was attempting to exit the parking lot of the Star Market, turning left from the exit. V2 was inattentive and failed to yield to oncoming traffic.

V2 sustained front end damage. V1 sustained front/right end damage to the passenger side of the vehicle.

Neither vehicle had airbag deployment. Neither of the operators sustained injury as a result of the collision.

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code 35

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate 36

Cargo Body Type Code 37 Gross Vehicle Weight 38

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 39

Hazmat Information:

Placard 40 Material 1 digit # 41 Material Name _____ Material 4 digit # _____ Release code 42

