

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

65 Ellis Street
UTILITY POLE 135-5
P.O.I.

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot
☐ Garage
☐ Mall/Shopping Center
☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

Operator of MV1 was traveling Northbound on Ellis Street when she stated she itched a sun burn, lost control of her vehicle and struck a utility pole near 65 Ellis Street. MV1 sustained moderate right fender and tire damage. MV1 was towed by AAA at owners request. No injuries. No damage to utility pole.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code