

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

Bridge St

California St

MV1

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

Operator of MV1 stated he was traveling westbound on California Street when another vehicle crossed him in the intersection. To avoid collision, he swerved and struck the curb at the northwest corner of the intersection. Officers were unable to locate the other vehicle. Operator of MV1 was evaluated by Fallon Ambulance and signed a patient refusal. The vehicle sustained heavy front end damage, front and side air bag deployment and a cracked windshield. David Donahue from Todys Towing responded and towed the vehicle. Newton Fire Engine 4 also responded for the fluid leak in the roadway.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

LAUREN MARIE KEEFE **NEWTON POLICE DEPARTMENT** **09/18/2021**

Police Officer Name (Please Print) Signature ID/Badge # Department Precinct/Barracks Date

CDP1 11 -24:00