

Police Use Only			Commonwealth of Massachusetts				RMV Document Number						
Date of Crash 10/10/2021		Time of Crash 15:56 24HR		City/Town NEWTON		Motor Vehicle Crash Police Report		Number Vehicles 2	Number Injured 0	Speed Limit 30 Latitude _____ Longitude _____		State Police <input type="checkbox"/> Local Police <input checked="" type="checkbox"/> MBTA Police <input type="checkbox"/> Other: <input type="checkbox"/>	
AT INTERSECTION:				< LOCATION >		NOT AT INTERSECTION:						9	
Route# Direction Name of Roadway/Street At				WEST 1121 WASHINGTON ST Route# Direction Address # Name of Roadway/Street Feet N S E W of _____ • _____ or _____ Mile Marker Exit Number								2	
Route# Direction Name of Intersecting Roadway/Street Also at Intersection with				Feet N S E W of _____ Route# Intersecting Roadway/Street								10	
Route# Direction Name of Intersecting Roadway/Street				Feet N S E W of _____ Landmark								11	
3				<input checked="" type="checkbox"/> Vehicle 1 1 #Occupants <input type="checkbox"/> Hit/Run <input type="checkbox"/> Moped Case Number 210000804								3	
License # --- St MA DOB/Age --- Sex M Lic. Class D 18 18 Lic. Restrictions 1 19 CDL Operator ROGERS CAMPBELL GARDNER Address 31 BROOKDALE RD City NEWTON State MA Zip 02460 Insurance Company THE COMMERCE INSURANCE				Reg # 1VTW45 Reg Type PAN Reg State MA Veh Year 2013 Veh Make VOLKSWAGEN Veh Config. 1 20 Owner (Same as operator) Address City State Zip Vehicle Action Prior to Crash 1 21 Damaged Area Code: (Circle Up to Three) Event Sequence 1 22 22 22 22 2 Most Harmful Event 1 23 Driver Contributing Code 19 24 24 Underride/Override 25 Towed Y								12	
Vehicle Travel Direction: N S E X Responding to Emergency? N Citation # (If Issued) Violation 1: Ch _____ Sec _____ Violation 2: Ch _____ Sec _____ Violation 3: Ch _____ Sec _____ Violation 4: Ch _____ Sec _____				 10 Undercarriage 11 Totaled								13	
Please fill out for operator and all occupants involved				Name (Last First Middle) Address Age/DOB Sex 26 Seat Pos. 27 Safety System 28 Airbag Status 29 Airbag Switch 30 Eject Code 31 Trap Code 32 Injury Status 33 Transp. Code Medical Facility								1	
Operator				See Above									
7				Please Select One of the Following: <input checked="" type="checkbox"/> Vehicle 2 1 #Occupants <input type="checkbox"/> Non-Motorist A Type 14 Action 15 Location 16 Condition 17 <input checked="" type="checkbox"/> Hit/Run <input type="checkbox"/> Moped								1	
License # --- St MA DOB/Age --- Sex M Lic. Class D 18 18 Lic. Restrictions 1 19 CDL Operator MULLEN CHRISTOPHER L Address 59 KENSINGTON ST City NEWTON State MA Zip 02460 Insurance Company THE COMMERCE INSURANCE				Reg # V727777 Reg Type CON Reg State MA Veh Year 2019 Veh Make HONDA Veh Config. 1 20 Owner (Same as operator) Address City State Zip Vehicle Action Prior to Crash 1 21 Damaged Area Code: (Circle Up to Three) Event Sequence 1 22 22 22 22 2 Most Harmful Event 1 23 Driver Contributing Code 1 24 24 Underride/Override 25 Towed Y								13	
Vehicle Travel Direction: N S E X Responding to Emergency? N Citation # (If Issued) Violation 1: Ch _____ Sec _____ Violation 2: Ch _____ Sec _____ Violation 3: Ch _____ Sec _____ Violation 4: Ch _____ Sec _____				 10 Undercarriage 11 Totaled									
Please fill out for operator and all occupants involved				Name (Last First Middle) Address Age/DOB Sex 26 Seat Pos. 27 Safety System 28 Airbag Status 29 Airbag Switch 30 Eject Code 31 Trap Code 32 Injury Status 33 Transp. Code Medical Facility									
Operator/Non-Motorist				See Above									

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

Crash Diagram: ie: → 1 → 2 →

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

The operator of MV1 stated that they were driving Westbound on Washington St. when they saw an open parking spot on the other side of the road. The operator of MV1 stated that they tried to make a U turn heading Eastbound to try to get the open parking spot. MV1 was on the first lane and did not see MV2 on the second lane. MV1 had major damage to the left side of the vehicle, and all airbags were deployed.

The operator of MV2 stated that they were driving Westbound on Washington St. when they saw MV1 attempt to make a U-Turn. MV2 stated that they did not have enough time to react which lead to the crash. MV2 had major damage to the front right side of the vehicle, and all airbags were deployed.

Both parties had no injures and denied medical treatment. Todys's arrived on scene and took possession of both motor vehicles.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

ELMER ACUNA

NEWTON POLICE DEPART

10/10/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date