


→ Direction 1 Vehicle 1 2 Vehicle 2 ⊕ Pedestrian
 ie: → 1 → 2 →

Crash Diagram:



If Crash Did Not Occur on a Public Way:

- Off-Street Parking Lot
- Garage
- Mall/Shopping Center
- Other Private Way

Indicate North by Arrow



Crash Narrative:

Mv 1 was traveling westbound on Beacon St when he swerved into the fence of 8 Manitoba Rd. After crashing into the fence, MV 1 pulled over on the right side of Manitoba Rd. The operator of MV 1 was approaching Manitoba Rd when he lost control of his power steering and his breaks did not function correctly. This caused him to strike the fence of 8 Manitoba Rd.

MV 1 sustained significant damage to the windshield, left front, and center front. MV 1 was towed by Tody's due to it being disabled. The operator of MV 1 sustained minor injuries to his right hand and was treated for concussion symptoms by Fallon medics. The operator of MV 1 was transported to Newton Wellesley Hospital by Fallon medics. The operator of MV 1 was issued citation T 1445545 MGL Ch 89/4a (Marked Lanes violation) in hand.

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

DONALD MURPHY

NEWTON POLICE DEPART

10/31/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department


Precinct/Barracks

Date

→ Direction 1 Vehicle 1 2 Vehicle 2  Pedestrian

Crash Diagram:

ie: → 1 → 2 → 



If Crash Did Not Occur on a Public Way:

- Off-Street Parking Lot
- Garage
- Mall/Shopping Center
- Other Private Way

Indicate North by Arrow



Crash Narrative:

The fence at 8 Manitoba Rd was damaged significantly, pieces of wood from the damage were across the front lawn of the residence. A black light pole was also struck in the collision. The lawn sustained tire mark damage from the collision as well. Photos of the damage to the fence, lawn, and light pole were taken with the camera in 495 and submitted to IT. I attempted to raise the residents of 8 Manitoba Rd with negative results. A note with the crash number of the incident was left on the front door of 8 Manitoba Rd.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

DONALD MURPHY

NEWTON POLICE DEPART

10/31/2021

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date