

Crash Narrative:

over the roadway, tearing it from its roots and landing on top of the truck. My observations indicate that the tree would have been leaning over the roadway as SWEET's tires were still in the roadway when the tree was struck. SWEET states the vehicle has a dash camera that records and could be accessed at a later date by the owner of the company.

Five pictures were taken of the crash scene and emailed to policerecords@newtonma.gov.

Property Damage:				
Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

ALAN JR RICHARD SOLOMAN.			NEWTON POLICE DEPARTM		11/03/2021
Police Officer Name (Please Print)	Signature	ID/Badge #	Department	Precinct/Barracks	Date
CDP1 11 :24:00					