

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 → Pedestrian

Crash Diagram:

Centre St

Homer St

MV#3

MV#2

MV#1

North Arrow

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

The operator of MV#1 stated he was travelling southbound on Centre St when his brakes failed and could not stop in time, striking MV#2 which pushed MV#2 into MV#3. MV#1 sustained minor damage to its front bumper. There were no reported injuries to the operator of MV#1. The operator of MV#1 did not have his license in his possession. He provided me with his information and an R.M.V query showed that he had a license status of suspended. While on scene I had the operator of MV#1 log on to his R.M.V account, pay off his balance owed and reinstate his driver's license (R.M.V confirmation #0-847-910-848). MV#1 was inspected and the brakes appeared to be in working order.

The operator of MV#2 stated she was travelling southbound on Centre St when she was struck from behind by MV#1 which pushed her vehicle into MV#3 in front of her. MV#2 sustained moderate damages to its rear and

(Continued on next page)

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length


Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

→ Direction 1 Vehicle 1 2 Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:



If Crash Did Not Occur
on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

Indicate North by Arrow



Crash Narrative:

front bumpers. The operator of MV#2 sustained non-incapacitating injury to her neck and refused medical attention.

The operator of MV#3 stated she was travelling southbound on Centre St when she was struck from behind by MV#2. MV#3 sustained minor damage to its rear bumper. There were no reported injuries to the operator of MV#3.

As of 05/12/2022, the license status of the operator of MV#1 is still suspended. I will mail MA uniform citation #T2012917 to the operator of MV#1 for violation of c90 s23 operating after suspended license.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

GITA K SETIABUDI

25111

NEWTON POLICE DEPART

05/09/2022

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date