

→ Direction 1 = Vehicle 1 2 = Vehicle 2 Pedestrian

ie: → 1 → 2 →

Crash Diagram:

Unit 1

2282 Commonwealth Avenue

Unit 1

P.O.L.

NOT TO SCALE

If Crash Did Not Occur on a Public Way:

☐ Off-Street Parking Lot

☐ Garage

☐ Mall/Shopping Center

☐ Other Private Way

Indicate North by Arrow

Crash Narrative:

Operator of MV1 states she was traveling west on Commonwealth Ave. after leaving the grocery store. She states she was feeling tired and must not have been paying attention. When she looked up she saw the grassy median and a telephone pole. She heard a pop and then swerved and MV1 rolled landing on its passenger side.

Operator of MV1 was evaluated by medics and signed a patient refusal.

It appears as if MV1 struck the curb with the left front tire, popping the tire and splitting the rim, also causing suspension damage. The vehicle then subsequently rolled onto its right side. Also possible striking the telephone pole. Eversource was notified to inspect pole. Todys up righted and towed MV1. NFD Engine 2 took care of the spill.

Witnesses:

Name (Last, First, Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last, First, Middle)	Address	Phone #	34-Type	Description of Damaged Property
EVERSOURCE, ,	160 CALVARY WALTHAM, MASSACHUSETTS		4	TELEPHONE POLE

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Carrier Issuing Authority Code

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ ICC #: _____ Interstate

Cargo Body Type Code Gross Vehicle Weight

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length

Hazmat Information:

Placard Material 1 digit # Material Name _____ Material 4 digit # _____ Release code

ALLAN L CICCONE, III NEWTON POLICE DEPARTM 06/06/2022

Police Officer Name (Please Print) Signature ID/Badge # Department Precinct/Barracks Date

CDP1 11 -24:00