
	Poli	ice Use Only		Common	ıwealtl	of M	[assa	achu	ise	tts			RMV	/ Docu	ıment	Number	
	Date of Crash 07/14/2022	Time of Crash 16:06	City/To	own M	otor V	ehicle	Cra	sh	Nun Vehi		Number Injured		d Limit		Sta	nte Police cal Police BTA Police	<u> </u>
	07/14/2022	24HR			Police	e Repo	<u>rt</u>		2		0		itude_		Otl	her:	
		AT INTER	RSECTION:	<	LOG	CATION	;	>			NOT	AT l	INTE	ERSE	CTI	ON:	\exists
		AUBUF	RNDALE AVE														- -
1 1	Route# Direc		Route# Direction Address # Name of Roadway/Street								et	_ - :					
At MURRAY RD Route# Direction Name of Intersecting Roadway/Street							Feet	N S E	W of	f		_ •		or			F
						Feet NSEW of Mile Marker or Exit Number											
	Also at Intersection with Route# Direction Name of Intersecting Roadway/Street						Feet N S E W of Route# Intersecting Roadway/Street										-
2 1							Feet N S E W of										
3	XVehicle1	_1_#Occupants	Hit/Run	Moped	Case Num	ber		22	200063	33							
	License#		St M	A DOB/Age	Re	g#RS16SB				F	Reg Typ	e PAN	1	Res	g State	MA	
	Sex_M Lic.	18 1		19		eh Year 2015		Vel	h Mak							20	-
4	Operator REC		OSCAR	Endorsn	nent	vner (Same											_ -
1	Address 15B N	MARIAN RD	First	Middle							First			Midd	lle		- L
	City FRAMIN		St	ate MA Zip 01702		Address City State Zip											
		npany ALLSTAT		r		-				21							_
5	1			onding to Emergenc	v? N Ev	Vehicle Action Prior to Crash Damaged Area Code: (Circle Up to Three Event Sequence 1 22 22 22 22 2 3											
		ssued)				ost Harmful		23					Ť			0 Undercarr	iage
		,		1 2: ChSec		iver Contrib	L		1 24	1	24		9		5 1	1 Totaled	
5 1	1			14: Ch Sec		Underride/Override 25 Towed N 8 7 6											
			ator and all occu														
	Name (Last Fir Operator	st Middle)		Addres See Abo			/DOB	Sex 1		ystem Sta	tus Switch	Code	Code	Status (Code	Medical Facili	ty .
	1										1				_		
												+					_
_																	
3	Please Select C of the Followi		2 <u>1</u> #Occupan	ts Non-Motori	st A Type	14 Actio		5 Loca	ation	16	Conditi	ion	17	۱	Hit/Rur	Мор	ed
	License# St TX DOB/Age				Re	g# MWP02	Reg Type_PAN				1	Reg State TX			_		
	Sex_M_ Lic. Class D 18 18 Lic. Restrictions 19 CDL					Veh Year 2008 Veh Make LEXUS Veh						Veh C	Config. 20				
8 1	Operator SYSOEV VASILY						Owner (Same as operator) Last First Middle									-	
_	Address 1551		Last First Middle Address										-				
	City DALLAS State TX Zip 75207						CityStateZip										-
	Insurance Com	Ve	ehicle Action	Prior to	Crash	1	21	Da	maged	l Area	Code:	(Circle	e Up to Thre	ee)			
	Vehicle Travel	ey? <u>N</u> Ev	Event Sequence 1 22 22 22 2 3 4 Most Harmful Event 1 23 10 Undercarriage 5 11 Totaled														
	Citation # (If I	М										iage					
	Violation 1: ChSecViolation 2: ChSec						Driver Contributing Code 1 24 24										
	Violatio	Uı	Underride/Override 25 Towed N 6														
			operator and al	l occupants involve			a/DOP		26 Seat Sa	27 2 afety Airl	28 29 bag Airbag	30 Eject	31 Trap		ransp.	Modinal E	
	Name (Last Fi Operator/	Non-Motorist		Addre See Abo		Ag	e/DOB	Sex	Pos. S		atus Switch	h Code 0	Code 0		Code l	Medical Facil	ity
									\top								\dashv
									\dashv	+							\dashv
									_	_				\vdash	_		\dashv
													1				



Crash Narrative:

MV1 operator stated he was operating westbound on Auburndale Ave approaching Murray Rd (both public ways

). MV1 operator stated he wanted to turn left onto Murray Rd southbound but missed the street. MV1

operator said he stopped, put his MV in reverse (going eastbound in reverse while in the westbound lane

) and struck MV2. MV1 rear left passenger bumper struck the right driver side front bumper causing damage

of MV2. MV1 operator was unsure how close MV2 was to him prior to the accident. MV1 operator reported no

injuries at this time, and no tow required.

MV2 operator stated he was following MV1 on Auburndale Ave westbound when he noticed MV1 stopping after

Murray Rd. MV2 stated MV1 then starting operating in reverse (eastbound in the westbound lane). MV2

operator stated MV1 rear left passenger bumper struck the right driver side front bumper of his MV causing

(Continued on next page)								
Witnesses:								
Name (Last, First, Middle)	Ade	dress			ſ	Phone #		Statement
Property Damage:								
Owner (Last, First, Middle)	Address		Phone #	34-Type	Description o	f Damage	ed Property	
Truck and Bus Information: Carrier Name	Registration #	·	(From Vehic	le Section)	Car	rier Issuin	ng Authority Coo	35 le
								le
Carrier Name		C	ity		St	<u>i</u>	Zip	le
Carrier Name		C	ity		St	<u>:</u>	Zip	le
Carrier Name	State Number	C	ity Issuing State	ICC#:_	St	<u>i</u>	Zip	le
Carrier Name	State Number	C	ity Issuing State	ICC#:_	St	<u>:</u>	Zip	le
Carrier Name	State Number	C Reg State	ity Issuing State	ICC#:_ Tra	St	39	Zip Interstate	le

-	Direction 1	■ Vehicle 1 2	2 = Vehicle 2	₽Pedestrian		
Crash Diagram:	ie: → 1	→ [2	2	₽Ŷ		
					If Crash <u>Did Not</u> On a Public Way:	ccur
		<u>_</u> 			☐ Off-Street Parking	Lot
					Garage	
		 			☐ Mall/Shopping Cer	nter
					☐ Other Private Way	
 			+		Indicate North by Arı	row
			+			
Crash Narrative:						
damage. MV2 operator esti		e to be worth	approximate	ly \$1,000 USD	MV2 operator reported	no
	tow required.					
Witnesses:						
Name (Last, First, Middle)		Address			Phone #	Statement
Property Damage:		-				
Owner (Last, First, Middle)	Address		Phone #	34-Type Des	scription of Damaged Property	
Truck and Bus Information:	Registration #		(From V	ehicle Section)		
Carrier Name					Carrier Issuing Authority Code	35
Address			City		St Zip	
US DOT #:	State Number		Issuing State	ICC #:	Interstate	36
Cargo Body Type Code 37 G	ross Vehicle Weight	38				
Trailer Reg #:	Reg Type	Reg State	Reg Year_	Trailer	Length 39	
Hazmat Information:	44					427
Placard 40 Material 1 digi	t# Material N	ame		Material 4 digit	# Release code	42
MARK HATFIELD			NEV	WTON POLICE DEPARTA	07/14/202	22
Police Officer Name (Please Print)	Signature	;		Department	Precinct/Barracks Date	

CDP1 11 ·24·00